

IRIS Touch Firmware Enhancements and Additions from Version 1.19.4 to Version 1.19.5

Overview

This document details enhancements to the feature set of the IRIS Touch from firmware Version 1.19.4 to Version 1.19.5.

This release (V1.19.5) is available on Chiron's reflash server with immediate effect. Due to normal manufacturing lead times, it will be introduced into new shipments over the course of the next few months. However, all IRIS Touch diallers can be upgraded by connecting them over IP to our reflash server, so you can be sure of having all the latest facilities, even if you have already taken delivery of the dialler. This can be done prior to install, at install or even after install.

Changes in this Release

Some minor enhancements have been made to version 1.19.4:

- 1) Improvements to the operation of enhanced roaming and preferred operator selection.
- 2) Upload/download access via direct TCP/IP call can be made to alarm panels connected to the IRIS dialler serial port (e.g. Texecom and Cooper). This resolves an issue reported in version 1.19.1.
- 3) Minor corrections to touch screen Finnish translations.



Chiron Security Communications Ltd

Wyvols Court, Swallowfield, Reading
Berkshire RG7 1WY, United Kingdom
Telephone: +44 0118 988 0228
Facsimile: +44 0118 988 1055
www.chironsc.com
Email: sales@chironsc.com

Registered office number: 6031811
2nd Floor, Aquis House, 49-51 Blagrove Street
Reading, Berkshire RG1 1PL United Kingdom
Chiron Security Communications Ltd
part of the Chi Holding group of companies 

How to Reflash

Connection to the reflash server can be instigated from the installer menu, Settings->Reflash:



The reflash IP address is set by default to Chiron's reflash server (195.59.117.164) and does not need to be changed unless another reflash server is to be used.